

# Illustrated Parts List - IPL Update



Product Name(s)

H135

Description of change

The functionality of the ignition module is improved. (MBU-49)

Comments

Fully interchangeable.

Introduced from

<b>Serial number / Date</b>	<b>Remark</b>
20152000002	New Ignition module 576 70 56-02 added. North America.
20153400385	New Ignition module 576 70 56-02 added.

IPL updates

<b>Page Title</b>	<b>Ref. no</b>	<b>New part no</b>	<b>Name</b>	<b>Excl. part no.</b>	<b>Remark</b>
Ignition system	7	576 70 56-02	Ignition module	576 70 56-01	